




2		1		
REVISIONS				
ZONE	REV.	DESCRIPTION	DATE	APPROVED
B5	A	Changed rivet head orientation; Rivet head opposite side assigned to two additional rivets. Orientation is required to clear elevator horn at full up elevator.	1.17.26	MCS

Revision Notice:
Install these two rivets with heads of rivets on opposite side, as shown here.

SHX-V03	1	Vertical Stab AFT Spar	SHX-V02	A
Assembly Number	QTY Required	Part Title	Next Assembly	
Sonex Highwing Vertical Stab AFT Spar Assembly				
Drawing Scale	Drawing/Assembly Number			Revision
1:3 & Noted	SHX-V03			A