


REVISIONS				
ZONE	REV.	DESCRIPTION	DATE	APPROVED
B5	A	Changed rivet head orientation; Rivet head opposite side assigned to two additional rivets. Orientation is required to clear elevator horn at full up elevator.	1.17.26	MCS
A5	B	Corrected bolt callouts; 6 bottom bolts corrected from AN3-7A to AN3-5A; 2 middle bolts corrected from AN3-7A to AN3-6A. BOM is unaffected by this correction.	1.26.26	MCS

D



Revision Notice:
Bolt lengths corrected
as-shown here.

SHX-V03	1	Vertical Stab AFT Spar	SHX-V02
Assembly Number	QTY Required	Part Title	Next Assembly
Sonex Highwing Vertical Stab AFT Spar Assembly			
Drawing Scale	Drawing/Assembly Number		Revision
1:3 & Noted	SHX-V03		B

A